

Improvements in heating, lighting, insulation and electricity generation 2004-2016:

- 2004: Storage heaters, poor insulation.**
- 2005: Lighting changed in meeting room.**
- 2006: Air-to-air heat pump (asap) & double glazing in meeting room.**
- 2007: Side walls of meeting room insulated.**
- 2008: Foyer & classrooms insulated; 3 ashps replaced 5 storage heaters; more double glazing**
- 2009: Walls insulated, windows double glazed, 1 ashp replaces 3 storage heaters, "warm roof"**
- 2010: Record cold winter**
- 2011: 60 PV panels on meeting house; more double glazing**
- 2016: LED lights in classrooms, kitchen, corridor.**
- 2017: PV panels on warden's bungalow.**

